
Mr. Dave Cole Page 4 of 4 February 23, 2009



Photos of Pier Failure/Damage

Photo 1. North Pier (looking southwest)




Photo 2. North Pier (looking northeast)

I:\dept\6\city of ames\trail bridge inspection.doc